stryker® Medical

CONFIDENTAL

2020 Scale Calibration

1. Turn scale lockout toggle off. (Located under footend control panel)
2. While holding down on the LBS./KG. button, switch the scale toggle back on.
3. Let up on the LBS./KG. button, the scale display should read "DOWNLOAD BARCODE".
4. Push the LBS./KG. button repeatedly until the display reads "INIT TO DEFAULTS".
5. Push and hold down on the Weight System On button until the display reads "DEFAULTS ENTERED".
6. Push the LBS./KG. button repeatedly until the display reads "CALIBRATE SCALE".
7. Push and hold down on the Weight System On button. Zero the bed, following the displayed instructions. When the bed is zeroed, the scale monitor will display REF X 100 = <2>0000. (This number represents 200 lbs.)
8. If the weight being used for calibration is not 200 lbs, the displayed number must now be changed to match the known weight. Change the REF number to equal the weight you will be placing on the bed for calibration (use weight near 200 lbs.), by using the LBS/KGS button to position the brackets (<>) around the digit that needs to be changed and the Lock/Unlock button to scroll through the bracketed digit.
9. After the number is corrected, press and release the Weight System On button. The scale display should read "ADD LBS, HIT ON".
10. Make sure the patient surface is flat. Place the calibrated weight in the center of the bed.
11. Push and release the Weight System On button. DO NOT TOUCH BED until the scale monitor reads CALIBRATE SCALE.
12. Push the LBS./KG. button repeatedly until the display reads "QUIT/SAVE".
13. Push and hold down on the Weight System On button until the display reads "SAVE COMPLETE". Release the Weight System On button. The bed scale will shut off after about one second.
14. Remove the calibrated weight from the bed. Turn the scale system on, zero the bed, and test the bed out for proper weight readings.